



Genuine Spicer® DSS40P Carrier Discontinuation, Replacement Options

Date: **August 1, 2019**

To: **All Dana Aftermarket Group Spicer® Heavy Axle Customers**

Affected Models: **DSS40P**

The DSS40P model carrier has been discontinued in the service and aftermarket space. Customers looking for replacement options can utilize the Dana DS461P model carriers **AND** choose between:

1. Purchasing new side gears, 120052, to utilize the existing shafts **OR**
2. Purchasing new axle shafts.

Old Part #	Description	Optional Replacement
DSS40P370CF	CORE FREE CARR 41I DSS40P 370	DS461P370CF
DSS40P355CF	CORE FREE CARR 41I DSS40P 355	DS461P355CF
DSS40P390CF	CORE FREE CARR 41I DSS40P 390	DS461P390CF
DSS40P411CF	CORE FREE CARR 41I DSS40P 411	DS461P411CF
DSS40P433CF	CORE FREE CARR 41I DSS40P 433	DS461P433CF
DSS40P456CF	CORE FREE CARR 41I DSS40P 456	DS461P456CF
DSS40P529CF	CORE FREE CARR 41I DSS40P 529	DS461P529CF

If you need additional information, please contact your Dana Aftermarket representative. Thank you for your continued support of Dana Aftermarket products!

Courtney McGuire
Associate Product Manager
Spicer® Heavy Axle Products

SpicerParts.com

Dana Aftermarket Group
PO Box 1000 Maumee, Ohio 43537
Warehouse Distributors: 1.800.621.8084
OE Dealers: 1.877.777.5360

Follow SpicerParts [f](#) [t](#) [@](#) [v](#) [in](#)